


ROSEDALE TREATMENT PLANT

Existing Condition 11/8/02



REACTION VESSEL


FILTER VESSEL



REACTION VESSEL
ACCESS HATCH (3)




FILTER VESSEL
ACCESS HATCH (4)



PNEUMATIC VALVES
AND MANIFOLD
PIPING



SITE ACCESS



EXISTING BACKWASH
RESERVOIR
(NOT INCLUDED IN
SCOPE OF WORK)

TANNERY TREATMENT PLANT


Existing Condition 11/8/02



SITE ACCESS



REACTION VESSEL
ACCESS HATCH (2)



FILTER VESSEL

REACTION VESSEL

MANIFOLD PIPING AND
PNEUMATIC VALVES



FILTER VESSEL ACCESS
HATCH (4)

