

Bid Results For: **Pringle Tank Recoat & Repair**

DATE: **July 10, 2007**

CWO: **07-142**

Bid Item No.	Description	Unit	Qty.	SCWD Estimate		Blastco, Inc. Torrance, CA		AA-1 Services, Inc. Paramount, CA		Crosno Construction, Inc. Arroyo Grande, CA	
				Unit Cost	Total Cost	Unit Cost	Total Cost	Unit Cost	Total Cost	Unit Cost	Total Cost
1	Mobilization	LS	1	\$6,760.00	\$6,760.00	\$5,000.00	\$5,000.00	\$4,000.00	\$4,000.00	\$18,000.00	\$18,000.00
2	Sample Tap Welding	EA	4	\$200.00	\$800.00	\$1,000.00	\$4,000.00	\$1,000.00	\$4,000.00	\$85.00	\$340.00
3	Preparation and Painting of Tank Interior Including Dehumidification Equipment and sound blankets	LS	1	\$103,745.00	\$103,745.00	\$91,500.00	\$91,500.00	\$104,000.00	\$104,000.00	\$123,800.00	\$123,800.00
4	Welding Repairs (per pit)	EA	10	\$100.00	\$1,000.00	\$150.00	\$1,500.00	\$300.00	\$3,000.00	\$85.00	\$850.00
5	Welding Repairs (per ft)	LF	10	\$70.00	\$700.00	\$100.00	\$1,000.00	\$500.00	\$5,000.00	\$85.00	\$850.00
6	Preparation and Painting of Tank Exterior	LS	1	\$22,880.00	\$22,880.00	\$16,900.00	\$16,900.00	\$15,900.00	\$15,900.00	\$10,000.00	\$10,000.00
7	Preparation and Painting of 84 sq. ft. galvanized metal building & 2 flex couplings	LS	1	\$2,000.00	\$2,000.00	\$750.00	\$750.00	\$4,000.00	\$4,000.00	\$850.00	\$850.00
8	Replace asphalt & caulking at tank base w/ 3/8" berm mix	LS	1	\$2,000.00	\$2,000.00	\$15,000.00	\$15,000.00	\$6,000.00	\$6,000.00	\$8,000.00	\$8,000.00
<b>Total</b>					<b>\$139,885.00</b>	<b>Total</b>	<b>\$135,650.00</b>	<b>Total</b>	<b>\$145,900.00</b>	<b>Total</b>	<b>\$162,690.00</b>

<b>Apparent Low Bidder</b>	<b>Blastco, Inc.</b>
<b>Low Bid</b>	<b>\$135,650.00</b>

Bid Item No.	Description	Unit	Qty.	Utility Service Co., Inc. Perry, GA		Paso Robles Tank, Inc. Paso Robles, CA		Spiess Construction Co. Santa Maria, CA	
				Unit Cost	Total Cost	Unit Cost	Total Cost	Unit Cost	Total Cost
1	Mobilization	LS	1	\$5,000.00	\$5,000.00	\$2,200.00	\$2,200.00	\$5,000.00	\$5,000.00
2	Sample Tap Welding	EA	4	\$500.00	\$2,000.00	\$880.00	\$3,520.00	\$1,100.00	\$4,400.00
3	Preparation and Painting of Tank Interior Including Dehumidification Equipment and sound blankets	LS	1	\$100,000.00	\$100,000.00	\$156,093.00	\$156,093.00	\$187,570.00	\$187,570.00
4	Welding Repairs (per pit)	EA	10	\$50.00	\$500.00	\$100.00	\$1,000.00	\$120.00	\$1,200.00
5	Welding Repairs (per ft)	LF	10	\$50.00	\$500.00	\$50.00	\$500.00	\$70.00	\$700.00
6	Preparation and Painting of Tank Exterior	LS	1	\$45,000.00	\$45,000.00	\$32,400.00	\$32,400.00	\$39,900.00	\$39,900.00
7	Preparation and Painting of 84 sq. ft. galvanized metal building & 2 flex couplings	LS	1	\$10,000.00	\$10,000.00	\$600.00	\$600.00	\$2,000.00	\$2,000.00
8	Replace asphalt & caulking at tank base w/ 3/8" berm mix	LS	1	\$10,000.00	\$10,000.00	\$9,000.00	\$9,000.00	\$9,000.00	\$9,000.00
<b>Total</b>					<b>\$173,000.00</b>	<b>Total</b>	<b>\$205,313.00</b>	<b>Total</b>	<b>\$249,770.00</b>